ECS Configuration C	nange Request				Page 1 of		Pag	ge(s)	
1. Originator	2. Log Date:	3. CCR #:	3. CCR #:		5. Tel:	6. R	m #:	7. Dept.	
Sarah Lewallen	6/12/03	03-04	19		301-925-0865	211	7B	SE	
8. CCR Title: Upgrade e0drg12 with 1GB memory for testing.									
9. Originator Signature/Date					11. Type:	1. Type: 12. Need Date: 6/1		: 6/19/03	
Sarah Lewallen /s/ 6/12/03			II		CCR				
13. Office Manager Signature/Date James Mather /s/ 6/12/03			14. Category of Update ECS Base		_	(11)		"Emergency"	
checklist):			17. Sche mpact: None	dule	18. CI(s) Af	18. CI(s) Affected:DRPHW			
19. Release Affected by this Change: 20. Date d			to Custo	mer:	21. Estimated Cost: None - Under 100K				
22. Source Reference: ⊠NCR (attach) □ Action Item □ Tech Ref. □ GSFC □ Other: ECSed37599									
23. Problem: (use additional Sheets if necessary) e0drg12 is taking 4 minutes to return results from a pwd on the archive									
24. Proposed Solution: (use additional sheets if necessary) As the first step in the problem determination, add 1 GB additional memory for testing the response time.									
25. Alternate Solution: (use additional sheets if necessary) Add additional swap space.									
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Will be limited to alternate solutions									
27. Justification for Emergency (If Block 15 is "Emergency"):									
28. Site(s) Affected: ☐ EDF ☐ PVC ☐ VATC ☒ EDC ☐ GSFC ☐ LaRC ☐ NSIDC ☐ SMC ☐ AK ☐ JPL ☐ EOC ☐ IDG Test Cell ☐ Other									
29. Board Comments:				30. \	Vork Assigned To	o: 31.	CCR (Closed Date:	
32. EDF/SCDV CCB Chair (Sign/Date):	•	•	App/Co	m. Disapproved	Withdrav	/ Fwd/	ESDIS ERB	
Fwd/ECS 33. M&O CCB Chair (Sign/Date): Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB									
Gary Gavigan /s/ 6/17/0			Fwd/ECS						
34. ECS CCB Chair (Sign/D	ate): Dis		Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS						

CM01JA00 Revised 8/2/02 ECS/EDF/SCDV/M&O